## **INSTALLATION INSTRUCTIONS**

### WD-1 Water Detector 9-30VAC/DC Power, Isolated N.C. switch output



# SEUVY

#### INSTALLATION

1. Install sensor in the area to be monitored such that probe pins will contact collected water.

2. Fasten sensor with screws provided, or other means.

3. Wire sensor as follows:

RED = Power Supply 9-30VAC/DC BLACK = Ground/Common

WHITE = N.C. (Form B) Switch GREEN = N.C. (Form B) Switch

Switch contact is electrically isolated from power supply.

#### **OPERATION**

Switch output opens when sensing probe pins are bridged by water.

Water resistance must be less than 1,000k (1M) ohms. Nearly all water supplies contain sufficient contaminants to trigger the sensor including: Filtered, Tap, Rain, Condensate, Melted Ice, Detergent, and Salt.

Not suitable for detecting distilled water.

Sensing probes utilize alternating current sensing (even when powered by DC current) to prevent electrolysis and oxidation of the sensing probes.

SPECIFICATIONS	
Power Supply	9-30VAC/DC, 10mA Max.
Output	N.C. (Form B) Solid State Relay, Isolated
Output Rating	30VAC/DC, 0.1A (100mA) Max.
Sensing	Gold plated electrodes
<b>Operating Environment</b>	-20 to 80degC


#### PRODUCT APPLICATION LIMITATION:

Senva products are not designed for life or safety applications. Senva products are not intended for use in critical applications such as nuclear facilities, human implantable device or life support. Senva is not liable, in whole or in part, for any claims or damages arising from such uses.

#### **IMPORTANT WARNINGS**

Only qualified trade installers should install this product
This product is not intended for life-safety applications
Do not install in hazardous or classified locations
The installer is responsible for all applicable codes
De-energize power supply prior to installation or service

#### DIMENSIONS



SEUVY